



FerrariDIY.com

Ferrari 355 Parts Cross Reference Guide

From: <http://www.ferrarichat.com/forum/showthread.php?t=333036>

Updated: 6/27/12

Items specific to 2.7 or 5.2 Motronic will be identified as such

Part Name	Part Number (s)	Source
Air Box, rubber mounts (F#142202)	V11Z02MMMKA025	Advanced Antivibration Components
Alternator, Rectifier	RN-10	Regitar, optional part for Alt rebuild
Alternator, Regulator	VRH2005-4A	Regitar
Brake Pads	????	Porsche 968
Coolant Recir Pump	3D0965561D	Parts4vws.com, not direct replacement, requires splicing
Coolant Temp Sender, 5.2	0 280 130 026	Bosch
Cooling Fan	30102050	SPAL, lower amp, slightly less air flow, longer life, no issues
Cooling Fan	30102113	SPAL, oem specs
CV Boot	????	Porsche , '78-83 Porsche 930
CV joint	93033203400	Porsche
Door mirror switch, 355 spider	V3SYR UL	Burgess, UK
Door, side mirror switch	4A0 959 565 D 01C	Audi
Engine lid gas struts	SG404018	Stabilus @ RockAuto.com, note: stronger, may damage welds
Engine lid gas struts	SG437007	Stabilus @ RockAuto.com
Exhaust Clamp (F#157474)	2.75"-3.06" stainless V clamp	OBX, ebay
Exhaust Gas Solenoid, EGR	EGR 140 or 7.02256.01.0	Fuelparts UK ltd, ebay/amazon or Pierburg
Exhaust Gasket (F#154984)	F7197	CarQuest
Exhaust Vacuum Valve	P997.111.680.00	Porsche, 997, requires mod., actuator rod 10mm to long and needs trimming, nut throws away.
Fuel Pressure Regulator	0 280 160 564	Bosch
Heater Control Valve	0 390 721 006	Bosch
Hood, front lift shocks	SG404018	Stabilus/Sachs
Idle Control Valve (F# 162406)	0 280 140 543	Bosch
Idle Speed Regulator, 5.2	0 280 140 543	Bosch
Mass Airflow Meter (MAF, 5.2)	0 280 217 800 / ?	Bosch / same as 540,740,840 BMW

Mass Airflow Meter, '95 (F#154916)	0 280 213 012	Bosch
O2 sensor, after car, 5.2	13820	Bosch @ RockAuto.com
O2 sensor, after cat, 5.2	15738	Bosch @ RockAuto.com universal part, requires splicing
O2 sensor, pre cat, 5.2	13819	Bosch @ RockAuto.com
O2 sensor, precat, 5.2	15730	Bosch @ RockAuto.com universal part, requires splicing
Power Steering Reservoir, early 355's	32-41-1-097-164	BMW
Relay, F1, tyco (v23134-b67-x152)	61361393403	BMW, E36 abs system
Shocks	rebuild	Deltavee.net, more expensive, but more robust according to Fchat members
Shocks	rebuild	Bilstein
Spark Plug Wires	custom	kingsborne.com
Spark Plugs, 2.7	PMR7A	NGK
Spark Plugs, 5.2	PMR8B	NGK
Throttle Position Potentiometer, 5.2	0 280 122 044	Bosch
Wheel Paint, Silver	95 8867 or NG GM 508	GM
Windshield, OEM Pilkington w/antenna and mirror clip	????	prosourceglassintl.com , remember to save your trim!

Please visit FerraryDIY.com to suggest an addition, edit or removal of items to/from this list. You can also find us on Facebook @ www.Facebook.com/FerrariDIY